

YIELD MONITORING AND MAPPING CAPABILITIES WITH THE FmX INTEGRATED DISPLAY

THE SAME DISPLAY THAT STEERS YOUR COMBINE CAN NOW COLLECT YOUR YIELD DATA.



SIMPLE INSTALLATION:

- Just connect the FmX™ display to existing combine sensors. No additional hardware needed
- Compatible with John Deere 60 and 70 series combines
- Able to collect data from the Ag Leader® YM2000

VARIABLE RATE:

- Record yield data to analyze performance and then create variable rate prescription maps using EZ-Office® software
- EZ-Office Pro software allows formulas to be used to automate prescription map creation
- Apply customized amount of seed and fertilizer throughout the field

MAPPING:

- Accurately monitor and map harvested crop yield and moisture to avoid harvesting high moisture areas that could cause grain storage problems
- Identify drainage or weed pressure areas of the field



TRANSFERABLE DATA:

- Yield data stored on an FmX display can easily be transferred to the office using a USB storage device
- EZ-Office software can then be used to evaluate field performance, identify problem areas and create variable rate prescription maps
- EZ-Office Pro software adds profit analysis and multi-year, averaging views of the yield data

ACCURATE AREA CALCULATIONS:

- Integrated system also performs accurate area calculations using auto cut width when the header is not full, providing an advantage for harvesting odd shape fields, point rows or areas already harvested
- No need to manually adjust actual cut width when not harvesting a full swath

SIMPLE USER INTERFACE:

- Familiar FmX integrated display used for steering and guidance
- Touch screen provides large buttons and map area



www.trimble.com

© 2009, Trimble Navigation Limited. All rights reserved. Trimble, the Globe & Triangle logo, and EZ-Office are trademarks of Trimble Navigation Limited, registered in the United States and in other countries. FmX is a trademark of Trimble Navigation Limited. All other trademarks are the property of their respective owners. PN 022503-675 (11/09)

Trimble Agriculture Division
10355 Westmoor Drive, Suite 100
Westminster, CO 80021 USA
+1-913-495-2700 Phone
+1-800-865-7438 Phone (US Toll Free)



Trimble Agriculture. The line everyone follows.